


MODEL TC1966D

CORRECTION NOTICE





R356, R357 and C181 were labeled incorrectly in the REVISION SUFFIX B service manual for TC1966D (PUB. NO. 37-92). For correct part description, see below.

REF. NO.	INCORRECT				CORRECT				
	PART. NO.	DESCRIPTION			PART. NO.	DESCRIPTION			
	R3K181561J	R, FUSE	560 0	HM 2W	R3K181561J	R, METAL	560	OHM	1W
△R357	R3K181221J	R, FUSE	220 0	HM 1/2W	R3K181221J	R, METAL	220	OHM	1W
C181	CHGTSL4G1J	CC	22 P	F 50V	CHGTSL4H1J	CC	22	PF	SOV

Please file this correction notice with the original version.

SERVICE PUBLICATION

#119-92